

transavia
Fluggesellschaft
Maintenance Review

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

0 Essentials

-6.81	AIRWORTHINES REVIEW CERT Group: 0 1 Remark: CAMO SÜDW.GEMACHT 10 NOV 2023		0 09.11.2023	0	12,00				
On Condition	PRÜFUNG ELEKTRONISCHE Group: 0 2 Remark:	AUSRÜSTUNG	NFL II-25/09	0 25.08.2020	0				
23.24	WÄGUNG DES FLUGZEUGES Group: 0 3 Remark:	WEIGHT AND BALANCE)		0 12.05.2023	0	48,00			
On Condition	PRÜFUNG KOMPASSANLAGEN Group: 0 4 Remark: NFL AUFGEHOBEN	NFL II-56/01		0 15.08.2020	0				

1 Phase Inspections

247	INSPECTION DOCUMENT MA Group: 1 0 Remark:	HR METER(2264,0)	NEXT DUE 2564,0	7569 31.07.2024 6725	300					
1044	INSPECTION DOCUMENT MC Group: 1 0 Remark:	CKPT SIDE WINDOW	EDDY CURRENT IN	7466 19.06.2024 0	1200					
296	INSPECTION DOCUMENT MD Group: 1 0 Remark:	NLG FORK		0 29.07.2022 6058			1000			
4646	INSPECTION DOCUMENT MF Group: 1 0 Remark:	CABIN LOWER SKIN		6268 14.12.2021 0	6000					
4646	INSPECTION DOCUMENT MG Group: 1 0 Remark:	FUSELAGE EXT SKIN		6268 14.12.2021 0	6000					
4646	INSPECTION DOCUMENT MH Group: 1 0 Remark:	CABIN DOORFRAME		6268 14.12.2021 0	6000					
6768	INSPECTION DOCUMENT MI Group: 1 0 Remark:	PRESSURE BULKHEAD		7190 25.08.2023 0	7200					
6768	INSPECTION DOCUMENT MJ Group: 1 0 Remark:	EMER. ESCAPE WINDSH		7190 25.08.2023 6481	7200					
278	INSPECTION DOCUMENT MK Group: 1 0 Remark:	VERT STABILIZER		0 13.03.1997 0	7900					
1978	INSPECTION DOCUMENT ML Group: 1 0 Remark:	AFT PRESS BULKHEAD		0 13.03.1997 0	9600					
7578	INSPECTION DOCUMENT MO Group: 1 0 Remark:	VERTICAL STABILIZER		0 13.03.1997 0	15200					
247	INSPECTION DOCUMENT 1 Group: 1 1 Remark:	COOL SYS HOURM CHK	ENG FIREX VISCK	7569 31.07.2024 6725	300					
0.53	INSPECTION DOCUMENT 2 Group: 1 2 Remark:	C352CS NEW INSTAL	I-21136284	7466 19.06.2024 6662		12,00				
0.53	INSPECTION DOCUMENT 2 Group: 1 2 Remark:	HAL 1.0 74-00	A034922	0 19.06.2024 0		12,00				

transavia
Fluggesellschaft
Maintenance Review

Fluggesellschaft

Maintenance Review

Page : 2

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

1 Phase Inspections

13.32		INSPECTION DOCUMENT 4	9912368-2	4828	7154 14.07.2023	6438		36,00			
		Group: 1 4	Remark: EMER GEAR BOTTLE TEST	TLL04/30							
18.35		INSPECTION DOCUMENT 5	30400031-1 ??	36969B1 ????	0 14.12.2021	0		60,00			
		Group: 1 5	Remark: LH ENG FIRE EXTINGUISHER BOTTL								
18.35		INSPECTION DOCUMENT 5	30400031-1 ???	70721B1 ???	6268 14.12.2021	0		60,00			
		Group: 1 5	Remark: RH ENG FIRE EXTINGUISHER BOTTL								
3.06		INSPECTION DOCUMENT 6	C352CS	I-21136284	7622 04.09.2024	6761		12,00			
		Group: 1 6	Remark: COCKPIT PORT FIRE EXT								
3.06		INSPECTION DOCUMENT 6	HAL 1.0 74-00	A034922	7622 04.09.2024	6761		12,00			
		Group: 1 6	Remark: FEUERLÖSCHER CABIN								
132.53		INSPECTION DOCUMENT 7	C352CS NEW INSTAL	I-21136284	7466 19.06.2024	6662		144,00			
		Group: 1 7	Remark: FEUERLÖSCHER COCKPIT OVERHAUL								
83.08		INSPECTION DOCUMENT 7	HAL 1.0	A034922	0 06.12.2022	0		120,00			
		Group: 1 7	Remark: FEUERLÖSCHER CABIN OVERHAUL					7,00			
247	13.91	INSPECTION DOCUMENT 8			7569 31.07.2024	6725	300	24,00			
		Group: 1 8	Remark:								
377	6.08	INSPECTION DOCUMENT 10			6799 06.12.2022	6184	1200	36,00			
		Group: 1 10	Remark:								
377	6.08	INSPECTION DOCUMENT 11	FUSELAGE SKIN JOINT	EDDY CURRENT 1	6799 06.12.2022	6184	1200	36,00			
		Group: 1 11	Remark:								
0.53		INSPECTION DOCUMENT 12	ARTEX 453-5000-999	11877	7466 19.06.2024	6662		12,00			
		Group: 1 12	Remark: ELT OPER.CHECK NEW UNIT	INSTAL							
12.53		INSPECTION DOCUMENT 13	GARMIN GTX 330	84412014	0 19.06.2024	0		24,00			
		Group: 1 13	Remark: XPDR 1 EASA SIB 2011-15								
12.53		INSPECTION DOCUMENT 13	GARMIN GTX 330	84412019	0 19.06.2024	0		24,00			
		Group: 1 13	Remark: XPDR 2 EASA SIB 2011-15								
12.53		INSPECTION DOCUMENT 13	STATIC TEST LH		0 19.06.2024	0		24,00			
		Group: 1 13	Remark:								
12.53		INSPECTION DOCUMENT 13	STATIC TEST RH		0 19.06.2024	0		24,00			
		Group: 1 13	Remark:								
12.53		INSPECTION DOCUMENT 13	70251N01D02	01010239CD	0 19.06.2024	0		24,00			
		Group: 1 13	Remark: LH ADC CALIBRATION TEST								
12.53		INSPECTION DOCUMENT 13	70251N01D02	00060162	0 19.06.2024	0		24,00			
		Group: 1 13	Remark: RH ADC CALIBRATION TEST								
12.53		INSPECTION DOCUMENT 13	RVSM		0 19.06.2024	0		24,00			
		Group: 1 13	Remark:								
12.53		INSPECTION DOCUMENT 13	44929-013	1190	0 19.06.2024	0		24,00			
		Group: 1 13	Remark: STDBY ALTIMETER								

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

1 Phase Inspections

13.91	INSP DOC 14 NDT L/H WHEEL	3-1527-2	1119	0	31.07.2024	0		24,00						
	Group: 1 14	Remark: 24M OR 6T/C TIRECHANGE: 1												
13.91	INSP DOC 14 NDT NOS WHEEL	3-1418 OPT4	7399	0	31.07.2024	0		24,00						
	Group: 1 14	Remark: 24M OR 6T/C TIRECHANGE: 2												
13.91	INSP DOC 14 NDT R/H WHEEL	3-1527-2	1084	0	31.07.2024	0		24,00						
	Group: 1 14	Remark: 24M OR 6T/C TIRECHANGE: 2												
347	INSPECTION DOCUMENT 17	30978-002	10604129	7569	31.07.2024	6725	400							
	Group: 1 17	Remark: BATT.INSTALLED 04.04.17 NEW												
97	INSPECTION DOCUMENT 18	PYLON FIREWALL INSP.		7569	31.07.2024	6725	150							
	Group: 1 18	Remark:												
547 13.91	INSPECTION DOCUMENT 21	WINDSHIELD BLEED AIR		7569	31.07.2024	6725	600	24,00						
	Group: 1 21	Remark:												
On Condition	INSPECTION DOCUMENT 22 LH	NOLONGER VAL SEE2.17	S4883T0479	4796	18.09.2018	4657								
	Group: 1 22	Remark: L/H NEW -6 PRECOOLER INSTALLED												
On Condition	INSPECTION DOCUMENT 22 RH	NOLONGER VAL SEE2.17	S4883T0456	4796	18.09.2018	4657								
	Group: 1 22	Remark: R/H NEW -6 PREECOLER INSTALLED												
6768	INSPECTION DOCUMENT 29	WINDSCHIELD SIDE CAB		7190	25.08.2023	0	7200							
	Group: 1 29	Remark:												
247 1.91	INSPECTION DOCUMENT 33	.		7569	31.07.2024	6725	300	12,00						
	Group: 1 33	Remark: CABIN DOOR INSPECTION												
On Condition	INSPECTION DOCUMENT 34	COOLING SYSTEM	NOT CURR.USED	0		0								
	Group: 1 34	Remark:												
On Condition	INSPECTION DOCUMENT 35	COOLING SYSTEM	NOT CURR.USED	0		0								
	Group: 1 35	Remark:												
-5.47	INSPECTION DOCUMENT 36	INCL. INSP. DOC. 02		7466	19.06.2024	6662		6,00						
	Group: 1 36	Remark: CORROSION INSPECTION												

2 Airframe

15738	NLG ASSEMBLY	6342000-21		0	13.03.1997	0			22500					
	Group: 2 2	Remark:												
5738	NLG FORK AND PISTON ASSY	63420000-3		0	13.03.1997	0			12500					
	Group: 2 3	Remark:												
15738	NLG ACTUATOR ASSEMBLY	9912370-3	197	0	13.03.1997	0			22500					
	Group: 2 4	Remark:												
7447	MLG TRUNNION ASSY	6341007-11	5142	2942	20.08.2014	3071			12480					
	Group: 2 6	Remark: LH							1342					
7447	MLG TRUNNION ASSY	9341007-12	3761	2942	20.08.2014	3071			12480					
	Group: 2 6	Remark: RH							1342					

transavia
Fluggesellschaft
Maintenance Review

Fluggesellschaft

Maintenance Review

Page : 4

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>2 Airframe</u>														
	6076	MLG ACTUATOR ASSEMBLY Group: 2 7 Remark:		9912397-6 LH	0536	2617	20.01.2008	2766			12000 1928			
	6155	MLG ACTUATOR ASSEMBLY Group: 2 7 Remark:		9912397-7 RH	777	780	07.03.2000	917			12000			
	58.56	EMER GEAR BOTTLE Group: 2 8 Remark:		9912368-2 NEW INSTALLATION DOM 04/2006	4828	2878	23.11.2009	3004					288,00 43,00	
1075		AFT ISOLATOR MOUNT LH Group: 2 10 Remark:	9912410-2			3697	29.04.2016	0	5000					
1075		AFT ISOLATOR MOUNT RH Group: 2 10 Remark:	9912410-2			3697	29.04.2016	0	5000					
1345		FWD ISOLATOR MOUNT LOW Group: 2 11 Remark:	9912410-3 LH			3967	29.04.2016	0	5000					
1075		FWD ISOLATOR MOUNT LOW Group: 2 11 Remark:	9912410-3 RH			3697	29.04.2016	0	5000					
1075		FWD ISOLATOR MOUNT TOP Group: 2 11 Remark:	9912410-3 LH			3697	29.04.2016	0	5000					
1075		FWD ISOLATOR MOUNT TOP Group: 2 11 Remark:	9912410-3 RH			3697	29.04.2016	0	5000					
	37.08	ENG FIRE EXTINGUISHER Group: 2 14 Remark:		CARTRIGES 13083-5 L/H AND R/H INBOARD + OUTBOARD	4 EA.	0	06.12.2022	0		72,00 5,00				
	25.81	ELT BATTERY Group: 2 15 Remark:		452-0133 BATT LABEL MAR/2027		6616	29.07.2022	6058					60,00	
On Condition		SCHLAUCHLEITUNGEN Group: 2 16 Remark:		NFL II-56/01 AUFGEHOBen		0		0						
374		PRECOOLER L/H TIME LIMIT Group: 2 17 Remark:	S4883T0479 NEW -6 PRECOOLER INST NO INSP			4796	18.09.2018	4657				3200		
374		PRECOOLER R/H TIME LIMIT Group: 2 17 Remark:	S4883T0456 NEW -6 PRECOOLER INST NO INSP.			4796	18.09.2018	4657				3200		
	23267	TRAILING LINK AND AXLE Group: 2 18 Remark:		6341002-7 LH	6861	2942	20.08.2014	3071			28300 1342			
	24609	TRAILING LINK AND AXLE Group: 2 18 Remark:		6341002-8 RH	5143	2942	20.08.2014	3071			28300			
	21538	OLEO ASSEMBLY Group: 2 19 Remark:		6341130-3 LH		0	13.03.1997	0			28300			
	22455	OLEO ASSEMBLY Group: 2 19 Remark:		6341130-3 RH		780	07.03.2000	917			28300			
7378		MAIN SPAR LWR CAP Group: 2 24 Remark:		WS 120.0 TO WS 152.0		0	13.03.1997	0	15000					

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

2 Airframe

	15738	TRUNNION SUPPORT FITTING	5513056-5		0	13.03.1997	0				22500			
		Group: 2 27	Remark: LH											
	15738	TRUNNION SUPPORT FITTING	5513056-6		0	13.03.1997	0				22500			
		Group: 2 27	Remark: RH											
	15738	NLG ACTUATOR SUP. FITTING	6511105-1		0	13.03.1997	0				22500			
		Group: 2 28	Remark:											
6378		HORIZON STAB FWD	UPPER SPAR CAB		0	13.03.1997	0	14000						
		Group: 2 29	Remark:											
5578		LWR MAIN SPAR SPLICE	WS 93.00		0	13.03.1997	0	13200						
		Group: 2 31	Remark:											
7378		LWR REAR SPAR SPLICE	WS 93.00		0	13.03.1997	0	15000						
		Group: 2 32	Remark:											
7378		MAIN SPAR CARRY THROUGH	RWS 42.0 TO LWS 42.0		0	13.03.1997	0	15000						
		Group: 2 33	Remark:											
7378		REAR SPAR CARRY THROUGH	RWS 42.0 TO LWS 42.0		0	13.03.1997	0	15000						
		Group: 2 34	Remark:											
7378		MAIN SPAR OUTB LWR CAP	WS 120 TO WS 152		0	13.03.1997	0	15000						
		Group: 2 35	Remark:											
	21538	AFT TRUNNION ATT. FITTING	6322070-13		0	13.03.1997	0				28300			
		Group: 2 36	Remark: LH AFT											
	21538	AFT TRUNNION ATT. FITTING	6322070-12		0	13.03.1997	0				28300			
		Group: 2 36	Remark: RH AFT											
	21538	FWD TRUNNION ATT. FITTING	6322060-11		0	13.03.1997	0				28300			
		Group: 2 37	Remark: LH FWD											
	21538	FWD TRUNNION ATT. FITTING	6322060-12		0	13.03.1997	0				28300			
		Group: 2 37	Remark: RH FWD											
	21538	SIDE BRACE FITTING LH	6322080-1		0	13.03.1997	0				28300			
		Group: 2 38	Remark: LH											
	21538	SIDE BRACE FITTING RH	6322080-2		0	13.03.1997	0				28300			
		Group: 2 38	Remark: RH											
32		A/C COMPR.DRIVE BRUSHES	2112,9	DUE 2288,5 HRM	7154	14.07.2023	0	500						
		Group: 2 39	Remark: HOUR METER CALC.LTA D-2013-153											

3 Engine N.1 L/H

243	ENGINE CHECK 1	LH	1366	7569	31.07.2024	6725	300							
	Group: 3 1	Remark:					4							
537	ENGINE CHECK 2	LH	1366	7569	31.07.2024	6725	600							
	Group: 3 2	Remark:					10							

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

3 Engine N.1 L/H

1837		ENGINE CHECK 3/5 Group: 3 3	LH Remark: HSI ENG TT 6216 AT INSTALL	1366	6459 27.04.2022	5943	3000							
1075		ENGINE CHECK 4 Group: 3 4	LH Remark: ENG TT 3454 AT INSTALLATION	1366	3697 29.04.2016	3473	5000							
On Condition		ENGINE COMPRESSOR Group: 3 6	COMPRESSOR WASH Remark: AS REQUIRED		0	0								
4181		ENGINE FUEL PUMP LH Group: 3 7	716700-5 Remark: LH	YYK0999	6803 14.12.2022	0	5000							
832		ENG.CNTL VLV ST.NOZZLE Group: 3 8	50803 Remark: LH	RF11974923	3454 01.04.2016	0	5000							
	8079	DISK, 1STG LP TURBINE Group: 3 9	50255 Remark: LH	RRL7FBAT	1421 13.05.2003	1415					14700 1274			
1725	3122	DISK, HP TURBINE Group: 3 10	59494 Remark: LH ENGINE 6216HRS/5706CYC	RRL7FBNT	6459 27.04.2022	5943	8000 5112				8000 4059			
	6879	DISK, 2STG LP TURBINE Group: 3 11	50792 Remark: LH	RRL7FBAF	1421 13.05.2003	1415					13500 1274			
	9738	FAN ROTOR 20 BLADE Group: 3 12	50333 Remark: LH	AU00343	0 21.11.1996	0					16500			
	1705	ROTOR, HP COMPRESSOR Group: 3 13	123505 Remark: LH	LC1302	3454 01.04.2016	3467					5000			
	4530	ROTOR, IP COMPRESSOR Group: 3 14	66032 Remark: LH	HW15084	1306 24.04.2003	1292					10000			
3837		FUEL CONTROL UNIT Group: 3 15	55629 Remark: LH ENGINE #1367	RF11423470	6459 27.04.2022	0	5000							
832		PUMP OIL-LUBE & SCAVENGE Group: 3 17	60689 Remark: LH	WL01542	3454 01.04.2016	0	5000							
-6		STARTER-GENERATOR OH Group: 3 19	300SGL129Q Remark: LH	6026XL2	6616 29.07.2022	0	1000							

4 Engine N.2 R/H

243		ENGINE CHECK 1 Group: 4 1	RH Remark:	1367	7569 31.07.2024	6725	300 4							
537		ENGINE CHECK 2 Group: 4 2	RH Remark: RH	1367	7569 31.07.2024	6725	600 10							
1837		ENGINE CHECK 3/5 Group: 4 3	RH Remark: RH ENG TT 6225 AT INSTALL	1367	6459 27.04.2022	5943	3000							
1075		ENGINE CHECK 4 Group: 4 4	RH Remark: ENG TT 3463 AT INSTALLATION	1367	3697 29.04.2016	0	5000							

transavia
Fluggesellschaft
Maintenance Review

Fluggesellschaft

Maintenance Review

Page : 7

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

4 Engine N.2 R/H

On Condition	ENGINE COMPRESSOR Group: 4 6 Remark: RH	COMPRESSOR WASH	AS REQUIRED	0	0						
3066	ENGINE FUEL PUMP Group: 4 7 Remark: RH	50797	YYK0093	6459	27.04.2022	0	5000 771				
841	ENG. CNTL VLV ST.NOZZLE Group: 4 8 Remark: RH	50803	RF2485837	3463	31.03.2016	0	5000				
8607	DISK, 1ST LP TURBINE Group: 4 9 Remark: RH	50255	RRL7S00484	6459	27.04.2022	5943			14700 5274		
373	376 DISK, HP TURBINE Group: 4 10 Remark: RH	59494	VORLAUF PRÜFEN RH ENGINE 6225HRS/5717CYC	6459	27.04.2022	5943	8000 6464		8000 6805		
7407	DISK, 2STG LP TURBINE Group: 4 11 Remark: RH	50792	RRL7S00588	6459	27.04.2022	5943			13500 5274		
9861	FAN ROTOR Group: 4 12 Remark: RH	50333	AU00344	1421	13.05.2003	1415			16500 1292		
1716	ROTOR, HP COMPRESSOR Group: 4 13 Remark: RH	123505	LC1299	3463	31.03.2016	3478			5000		
4545	ROTOR, IP COMPRESSOR Group: 4 14 Remark: RH	66032	HW15095	1315	24.04.2003	1307			10000		
3837	FUEL CONTROL UNIT Group: 4 15 Remark: RH	55629	RF13085039	6459	27.04.2022	0	5000				
841	PUMP OIL-LUBE & SCAVENGE Group: 4 17 Remark: RH	60689	WL01323	3463	31.03.2016	0	5000				
650	STARTER-GENERATOR OH Group: 4 19 Remark: RH	300SGL129Q	7084XL2	7272	26.10.2023	6542	1000				

7 Various

40.87	PBE PROT.BREATH.EQUIPMENT Group: 7 3 Remark:	15-40F-80	93912003	0 31.10.2018 0	120,00			
4.77	FIRST AID KIT INSPECTION Group: 7 5 Remark:	CAT.IDE.A.220 INSP.IN DOC 2 ENTHALTEN		0 26.10.2024 0	12,00			
37.88	CREW OXYGEN MASK L/H Group: 7 21 Remark:	MC10-16-101 DMF 07/22	B183136	0 01.03.2023 0	72,00 7,00			
27.78	CREW OXYGEN MASK R/H Group: 7 22 Remark:	MC10-16-101	B162827	6180 27.09.2021 0	72,00			
0.51	OXYGEN BOTTLE HYDSTAT TST Group: 7 23 Remark:	176421-50 HYDROSTATIC TEST	39938001	5550 29.07.2020 5261	60,00 1,30			
-2.50	OXYGEN BOTTLE TIME LIMIT Group: 7 23 Remark:	176421-50 NEW INSTALLATION	39938001	2905 23.03.2010 3032	180,00			

transavia
Fluggesellschaft
Maintenance Review

Fluggesellschaft

Maintenance Review

Page : 8

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
-----	-----	-----	-------------	-----	-----	-----	-----	-----	------------	------------	------------	------------	------------	------------

7 Various

0.53	LPV/VNAV CONVERTER Group: 7 24 Remark:	AVIONIK STRAUBING WIRING INSPECTION	0 19.06.2024 0	12,00				
101.56	LIFE VEST EAM XF35 Group: 7 31 Remark:	P01074-207C PILOT L/H	23111260022	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST EAM XF35 Group: 7 32 Remark:	P01074-207C CO PILOT R/H	23111260023	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST EAM XF35 Group: 7 33 Remark:	P01074-207 CABIN	24051630279	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST EAM XF35 Group: 7 34 Remark:	P01074-207 CABIN	240511630280	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST EAM XF35 Group: 7 35 Remark:	P01074-207 CABIN	24051630281	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST EAM XF35 Group: 7 36 Remark:	P01074-207 CABIN	24051630282	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST EAM XF35 Group: 7 37 Remark:	P01074-207 CABIN	24051630283	0 31.07.2024 0	120,00 8,35			
101.56	LIFE VEST RAM XF35 Group: 7 38 Remark:	P01074-207 CABIN	24051630284	0 31.07.2024 0	120,00 8,35			

8 LTA

On Condition	AD 06-29 Group: 8 0 Remark: SAIB NM-06-09	COMPLETE	2803 29.10.2008 0						
On Condition	AD 2011-0090 R1 Group: 8 0 Remark: EROS OXYGEN MASK REGULATOR	COMPLETE	2836 06.02.2012 0						
On Condition	AD 38-01 Group: 8 0 Remark: WASTE RECEPACLE INSP.	COMPLETE	1048 02.05.2001 0						
On Condition	AD 97-01-05 Group: 8 0 Remark: WILLIAMS FJ 44-1	HP TURBINE N/A BY S/N	0 06.01.1997 0						
On Condition	EASA 2005-0021 Group: 8 0 Remark: EASA AD2005-0021	23AD-15 N/A	1967 16.09.2005 0						
On Condition	EASA 2006-0269 Group: 8 0 Remark: MODIFICATION MODE S XPDR	COMPLETE	0 29.08.2014 0						
On Condition	EASA 2008-0159 Group: 8 0 Remark: MOD/REPL. MODE S XPDR HONEYWEL	COMPLETE	0 29.08.2014 0						
On Condition	EASA 2009-0251-E Group: 8 0 Remark: EASA AD2009-0251-E FIRE EXT	26AD-20 N/A	2905 23.03.2010 3032						
On Condition	EASA 2009-0262 R1 Group: 8 0 Remark: HALON 1211 FIRE EXT	N/A	2905 23.03.2010 3032						

transavia
Fluggesellschaft
Maintenance Review

Fluggesellschaft

Maintenance Review

Page : 9

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>8 LTA</u>														
On Condition	EASA 2009-0278 Group: 8 0			Remark: PORT. HALON FIRE EXT	N/A	2905	23.03.2010	3032						
On Condition	EASA 2010-0003 R2 (1-7) Group: 8 0			Remark: EXEMPTION CESSNA C525	N/A	0		0						
On Condition	EASA 2010-0062 R1 Group: 8 0			Remark: HALON 1211 FIRE EXT	N/A	2909	17.06.2010	3036						
On Condition	EASA 2012-0254 (1-3) Group: 8 0			Remark: NOT APPLICABLE DUE P/N	N/A	2942	02.09.2014	3071						
On Condition	EASA 2013-0020 (1) Group: 8 0			Remark: ORIGINAL SEAT BELTS INSTALLED	N/A	2942	02.09.2014	3071						
On Condition	EASA 2013-0020 (2) Group: 8 0			Remark: ORIGINAL SEAT BELTS INSTALLED	N/A	2942	02.09.2014	3071						
On Condition	EASA 2013-0020 (3) Group: 8 0			Remark: ORIGINAL SEAT BELTS INSTALLED	N/A	2942	02.09.2014	3071						
On Condition	EASA 2013-0020 R1 TO R4 Group: 8 0			Remark: ORIGINAL SEAT BELTS INSTALLED	N/A	2942	02.09.2014	3071						
On Condition	EASA 2014-0019 (1-4) Group: 8 0			Remark: SUPERSEDED BY EASA AD2014-0095	N/A	2942	20.08.2014	3071						
On Condition	EASA 2014-0088 Group: 8 0			Remark: COCKPIT VOICE RECORDER	N/A	0		0						
On Condition	EASA 2014-0088 (1) Group: 8 0			AP71232101OR1101 Remark: REMOVE THE TEAM CVR	N/A	0	19.04.2014	0						
On Condition	EASA 2014-0088 (2) Group: 8 0			Remark: AP71232101 OR AP71231101	N/A	0		0						
On Condition	EASA 2014-0095 (1-5) Group: 8 0			Remark: EQUIPMENT NOT INSTALLED	N/A	2942	20.08.2014	3071						
On Condition	EASA 2014-0095 R1 (1-5) Group: 8 0			Remark: EQUIPMENT NOT INSTALLED	N/A	2942	02.09.2014	3071						
On Condition	EASA 2014-0125 (1-7) Group: 8 0			Remark: MANDATORY		0		0						
On Condition	EASA 2014-0142 (1-3) Group: 8 0			Remark: NOT APPLICABLE DUE S/N	N/A	2942	02.09.2014	3071						
On Condition	EASA 2014-0142 R1 (1-3) Group: 8 0			Remark: NOT APPLICABLE DUE S/N	N/A	2942	20.08.2014	3071						
On Condition	EASA 2014-0187 (1-4) Group: 8 0			Remark: BY MANUFACTURE SAF.BELT ATT.BO	N/A	2942	28.08.2014	3071						
On Condition	EASA 2014-0254 R1 (1-3) Group: 8 0			Remark: NOT APLLICABLE DUE P/N	N/A	2942	20.08.2014	3071						

transavia
Fluggesellschaft
Maintenance Review

Engine No. 1 : 6762

Engine No. 2 : 6762

Page : 10

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>8 LTA</u>														
On Condition			EASA 2014-0279 Group: 8 0	Remark:	EQUIPMENT/FURNISHING REST.SYS	0		0						
On Condition			EASA 2014-0279 (1) Group: 8 0	Remark:	INSP. LABEL ROTARY SUB ASSY.	0		0						
On Condition			EASA 2014-0279 (1.1) Group: 8 0	Remark:	REPL. ROTARY BUCKLE SUB-ASSY.	0		0						
On Condition			EASA 2014-0279 (1.2) Group: 8 0	Remark:	MARK SEAT INOP. UNTIL REPL.ROT	0		0						
On Condition			EASA 2014-0279 (2) Group: 8 0	Remark:	SB358/SB-14-101 REPL.EACH ROTARY BUCKLE SUB-AS	0		0						
On Condition			EASA 2014-0279 (3) Group: 8 0	Remark:	SB358/SB-14-101 DO NOT INST. ANY REST.SYS.	0		0						
On Condition			FAA 1974-08-09 R3 Group: 8 0	Remark:	NO LAVATORY DOOR INS N/A NO FAR 25 LAVATORY RECEPTABLE FIRE PREVE	0	28.03.2012	0						
On Condition			FAA 1997-05-03 Group: 8 0	Remark:	34AD-01 ALLIED GNS-XLS	COMPLETE	134	28.10.1997	0					
On Condition			FAA 1997-08-09 R2 Group: 8 0	Remark:	SUPERSEDED FAA 1974-08-09 R3	COMPLETE	2909	12.05.2010	3036					
On Condition			FAA 1998-25-02 Group: 8 0	Remark:	34AD-02 BFGOODRICH SKYWATCH SKY497	COMPLETE	564	12.04.1999	0					
On Condition			FAA 1998-25-10 Group: 8 0	Remark:	25AD-01 AIRCRAFT BELT INC	COMPLETE	564	12.04.1999	0					
On Condition			FAA 1999-07-04 Group: 8 0	Remark:	DISK RIM FAILURE P/N 55291	COMPLETE	830	24.05.2000	982					
On Condition			FAA 1999-07-04 Group: 8 0	Remark:	DISK RIM FAILURE P/N 55291	COMPLETE	830	24.05.2000	982					
On Condition			FAA 1999-08-21 Group: 8 0	Remark:	35AD-01 PURITAN BENNETT AERO SYS.	COMPLETE	824	19.05.2000	0					
On Condition			FAA 2001-23-17 Group: 8 0	Remark:	34AD-04 GARMIN GNS 430 NOT APPLICABLE	COMPLETE	1153	17.01.2002	0					
On Condition			FAA 2002-20-09 Group: 8 0	Remark:	31AD-01 COLLINS AFD-3010 NOT APPLICABL	COMPLETE	1376	10.02.2003	0					
On Condition			FAA 2003-13-08 Group: 8 0	Remark:	34AD-05 TAWS 8000 EQUIPMENT NOT INST	COMPLETE	1465	21.07.2003	0					
On Condition			FAA 2003-21-07 Group: 8 0	Remark:	27AD-01 ELEC. TRIM FAILURE	COMPLETE	1567	19.01.2004	0					
On Condition			FAA 2004-08-15 Group: 8 0	Remark:	34AD-06 TAWS 8000 EQUIPMENT NOT INST	COMPLETE	1645	04.05.2004	0					

Registration: D-ITRA	Cycles Airframe : 6762	<i>transavia</i> Fluggesellschaft Maintenance Review
Typ : CESSNA C525	Engine No. 1 : 6762	
Date : 03.06.25	Engine No. 2 : 6762	
Hours : 7622 h	Page : 11	

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

8
LTA

On Condition	FAA 2006-16-18 Group: 8 0	Remark: SANDEL AVIONICS MODEL ST3400	34AD-12	NOT INSTALLED	2262	27.10.2006	0							
On Condition	FAA 2010-01-03 Group: 8 0	Remark: SERVICE ALL FIRE EXT & REPL		N/A	2905	23.03.2010	3032							
On Condition	FAA 2010-04-16 Group: 8 0	Remark: REPL. ALL H1-10 AIR HALON FIRE		N/A	2909	17.06.2010	3036							
On Condition	FAA 2011-14-08 Group: 8 0	Remark: B/E AEROSPACE FLOW PAX MASK		COMPLETE	2836	06.02.2012	0							
On Condition	FAA 2012-02-08 Group: 8 0	Remark: ACSS AND TCAS UNITS	UNIT NOT INSTALLED	N/A	0	13.03.2012	0							
On Condition	FAA 2014-05-27 Group: 8 0	Remark: MODE S XPDR TEST & CALIBRATION	INSP. DOCUMENT 13	N/A	0	02.05.2014	0							
On Condition	FAA 2014-18-01 Group: 8 0	Remark: MODE S XPDR INSP.			0		0							
On Condition	LTA 1996-166 Group: 8 1	Remark: SB CANCELLED 03/1997	SB FJ44-A74-3	ENGINES N/A	0	23.05.1996	0							
On Condition	LTA 1997-123 Group: 8 1	Remark: S/N 0-153 ONLY		N/A BY S/N	0		0							
On Condition	LTA 2001-086 Group: 8 1	Remark:		N/A	0		0							
On Condition	LTA 2019-103 Group: 8 1	Remark: ATLAS WINGLETS NOT INSTALLED	AD 2019-0086E	WINGLETS N/A	0	23.04.2019	0							
On Condition	LTA D-2003-379R1 Group: 8 1	Remark: CORR.ELEK.PITCH TRIM SYS.	US--2004-14-20 27AD-	COMPLETE	1696	26.08.2004	0							
On Condition	LTA D-2006-20 Group: 8 1	Remark: SERVICE ALL FIRE EXT & REPL.	US-2005-17-11 26AD-0	COMPLETE	2905	23.03.2010	3032							
On Condition	LTA D-2008-129 Group: 8 1	Remark: INSP.LOWER SKIN STRUCTURE	53AD-01	N/A	2682	04.06.2008	0							
On Condition	LTA D-2008-252 Group: 8 1	Remark: INSP.AFT FIREWALL SEALANT	US-2008-12-01 54AD-0	N/A	2803	29.10.2008	0							
On Condition	LTA D-2012-237R1 Group: 8 1	Remark: BRANDSCHUTZ TOILETTENRAUM	BRANDSCHUTZ TOIL	N/A NO T-RAUM	0		0							
447	LTA D-2013-153 Group: 8 1	Remark: INSP.A/C MOTOR BRUSHES	US-2013-08-05	DUE @2764,0 HR	7569	31.07.2024	0	500						

9
SB

On Condition	ASB FJ44-A72-038 R1 Group: 9 0	Remark: HP TURBINE DISK REVISE		COMPLETE	0		0							
--------------	-----------------------------------	--------------------------------	--	----------	---	--	---	--	--	--	--	--	--	--

transavia
Fluggesellschaft
Maintenance Review

Engine No. 1 : 6762

Engine No. 2 : 6762

Page : 12

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9 SB</u>														
On Condition			ASB FJ44-A72-038 R1 Group: 9 0 Remark:	HP TURBINE DISK REVISE	COMPLETE	0		0						
On Condition			ASL 525-21-01 Group: 9 0 Remark:	21SLA01 A/C GROUND CABLE INSP.	COMPLETE	1103	25.09.2001	0						
On Condition			ASL 525-27-02 Group: 9 0 Remark:	ELEC.ELEV. TRIM RUNAWAY PROC.	COMPLETE	1546	05.12.2003	0						
On Condition			ASL 525-32-21 Group: 9 0 Remark:	GOODRICH SERVICE BULLETIN MLG	COMPLETE	2851	13.08.2009	0						
On Condition			ASL 525-34-13 Group: 9 0 Remark:	FLAT PANEL CONTROL DISPLAY	COMPLETE	1164	08.02.2002	0						
On Condition			ASL 525-52-01 Group: 9 0 Remark:	EMER-DOOR INSP.	COMPLETE	2617	20.01.2008	0						
On Condition			ASL 525-53-03 R3 Group: 9 0 Remark:	RELIEF TUBE CORROSION	N/A	0		0						
On Condition			ASL 525-53-04 R5 Group: 9 0 Remark:	EQUIPMENT NOT INSTALLED	N/A	0		0						
On Condition			ASL 525-73-06L Group: 9 0 Remark:	WILLIAMS ROLLS SB FJ44-A73-12	COMPLETE	0		0						
On Condition			ASL 525-73-06R Group: 9 0 Remark:	WILLIAMS ROLLS SB FJ44-A73-12	COMPLETE	0		0						
On Condition			SB 525-11-09 Group: 9 0 Remark:	11SB-09 FUEL PLACARD RELOCATION	N/A	0		0						
On Condition			SB 525-21-12 Group: 9 0 Remark:	21SB-12 DUMP WIRING MOD.SW.GUARD INST.	COMPLETE	362	27.08.1998	0						
On Condition			SB 525-21-13 Group: 9 0 Remark:	21SB-13 : 525R1 EVAPORATOR WATER COLL.& DRAIN.	N/A	0		0						
On Condition			SB 525-21-15 Group: 9 0 Remark:	21SB-15 BINARY PRESS.SWITCH REPLACE	COMPLETE	1261	15.05.2002	0						
On Condition			SB 525-21-17 (R2,R3) Group: 9 0 Remark:	21SB-17 FWD EVAPORATOR REPL. INST.	N/A	0		0						
On Condition			SB 525-21-19 Group: 9 0 Remark:	21SB-19 TEMP SENSOR RELOCATION	N/A	0		0						
On Condition			SB 525-21-20 (R1) Group: 9 0 Remark:	N/A BARO.PRESS.SWITCH INST.	N/A	0		0						
On Condition			SB 525-23-08 Group: 9 0 Remark:	23SB-08 ALLIEDSIGNAL 8,33KHZ COM.INST.	COMPLETE	682	28.09.1999	0						
On Condition			SB 525-23-12 Group: 9 0 Remark:	23SB-12 HONEYWELL KY-169A/B VHF COMM	COMPLETE	1696	26.08.2004	0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9 SB</u>														
On Condition			SB 525-23-13 Group: 9 0	Remark: 23SB-13 GARMIN RADIO REPLACEMENT	N/A	0		0						
On Condition			SB 525-23-22 Group: 9 0	Remark: EMER.GEAR RELEASE BRAKET	COMPLETE	1261	15.05.2002	0						
On Condition			SB 525-24-14 R1 Group: 9 0	Remark: 24SB-14 : 525R1 GCU START MODIFICATION	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-24-15 Group: 9 0	Remark: 24SB-15 CB TERMINAL SCREW LENGTH INSP.	COMPLETE	824	19.05.2000	0						
On Condition			SB 525-24-17 R1 Group: 9 0	Remark: 24SB-17 : 525R1 EXT.PWR. REVERSE POL.PROTECT.	N/A	0		0						
On Condition			SB 525-24-19 R2 Group: 9 0	Remark: 24SB-19 : 525R2 CONCORDE LEAD ACID BATT.INST.	N/A	0		0						
On Condition			SB 525-24-22 Group: 9 0	Remark: 24SB-22 TAILCONE ELEC. GD.STUD IMPROVE	COMPLETE	1696	26.08.2004	0						
On Condition			SB 525-24-23 Group: 9 0	Remark: 24SB-23 AFT CABIN WIRE BUNDLE PROTECT.	COMPLETE	2209	06.09.2006	0						
On Condition			SB 525-24-25 Group: 9 0	Remark: 24SB-25 NICKE CADMIUM BATT INST.	N/A	0		0						
On Condition			SB 525-25-22 R1 Group: 9 0	Remark: 25SB-22 : 525R1 GLARESHIELD LEATHER STRAP INST	N/A	0		0						
On Condition			SB 525-25-23 Group: 9 0	Remark: 25SB-23 ELT	COMPLETE	1696	26.08.2004	0						
On Condition			SB 525-25-25 Group: 9 0	Remark: SB 08-22-2007 CANCEL TOILET TRAY AND PAD INST.	N/A	0		0						
On Condition			SB 525-25-26 Group: 9 0	Remark: 25SB-26 PAX SEAT GEAR&BACKREST PIN REP	N/A	0		0						
On Condition			SB 525-26-01 Group: 9 0	Remark: 26SB-01 FIRE BOTTLE IDENT.SLEEVE INST.	COMPLETE	1894	30.05.2005	0						
On Condition			SB 525-27-06 Group: 9 0	Remark: 27SB-06 TRIM ACTUATOR GREASE FITT INST	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-27-07 Group: 9 0	Remark: N/A HYD.SYS. RESTRICTOR REPL./INST	N/A	0		0						
On Condition			SB 525-27-11 Group: 9 0	Remark: COMPLETE STEEP APP.CERT.SPEED BRAKE ADJ	COMPLETE	824	19.05.2000	0						
On Condition			SB 525-27-15 R1 Group: 9 0	Remark: COMPLETE FLAP OVERRIDE SWITCH INST.	COMPLETE	1696	26.08.2004	0						
On Condition			SB 525-27-17 Group: 9 0	Remark: COMPLETE ELEC.ELEV.TRIM PCB REPL.	COMPLETE	1696	26.08.2004	0						

transavia
Fluggesellschaft
Maintenance Review

Fluggesellschaft

Maintenance Review

Page : 14

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>9 SB</u>														
On Condition			SB 525-27-18 Group: 9 0	Remark: ELEVATOR TRIM POINTER REPL.	N/A	0		0						
On Condition			SB 525-27-19 R2 Group: 9 0	Remark: ELEV.TRIM CABLE THICK.CHANGE	COMPLETE	2942	20.08.2014	3071						
On Condition			SB 525-27-20 Group: 9 0	Remark: ELEV. TRIM POINTER ASSY IMPROV	N/A	0		0						
On Condition			SB 525-27-26 R1 Group: 9 0	Remark: FLT CONTR.TAILCONE STRINGER	CKD IMPLEMENTED	0		0						
On Condition			SB 525-28-10 Group: 9 0	Remark: FUEL XFEED FUEL TRANSFER MOD.	N/A	0		0						
On Condition			SB 525-28-11 R1 Group: 9 0	Remark: WING FUEL BOOST PUMP WIRE ROUT	N/A	1967	16.09.2005	0						
On Condition			SB 525-28-12 Group: 9 0	Remark: WING FUEL BOOST PUMP WIRE IMPR	COMPLETE	1696	26.08.2004	0						
On Condition			SB 525-28-12 R1 Group: 9 0	Remark: WING FUEL BOOST PUMP WIRE IMPR	COMPLETE	2942	20.08.2014	3071						
On Condition			SB 525-29-09 Group: 9 0	Remark: HYD. LINE IMPRO.	COMPLETE	975	27.10.2000	0						
On Condition			SB 525-29-10 Group: 9 0	Remark: SOLENOID LOADING VALVE REPL.	COMPLETE	1261	15.05.2002	0						
On Condition			SB 525-29-11 R2 Group: 9 0	Remark: SB CANCELLED	N/A	0		0						
On Condition			SB 525-29-14 R1 Group: 9 0	Remark: HYD.PWR. RELIEF VALVE STAKING	COMPLETE	2836	06.02.2012	0						
On Condition			SB 525-29-15 Group: 9 0	Remark: HYD.PWR STAINLESS STEEL TUBE	N/A	0		0						
On Condition			SB 525-30-06 Group: 9 0	Remark: WING ANTI-ICE OVER TEMP SWITCH	COMPLETE	824	16.05.2000	0						
On Condition			SB 525-30-07 R2 Group: 9 0	Remark: WING ANTI-ICE OVER TEMP SWITCH	N/A	0		0						
On Condition			SB 525-32-06 R1 Group: 9 0	Remark: GRAVEL RWY OPTION MOD	N/A	0		0						
On Condition			SB 525-32-14 Group: 9 0	Remark: MLG TRUNNION PIN REPL	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-32-15 Group: 9 0	Remark: LANDING GEAR ANTISKID DIODE	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-32-17 Group: 9 0	Remark: LANDING GEAR BRAKE LINE REPL.	COMPLETE	455	20.12.1998	0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9 SB</u>														
On Condition			SB 525-32-17 R1 Group: 9 0	Remark: BRAKE LINE REPLACEMENT	COMPLETE	1392	05.04.2003	0						
On Condition			SB 525-32-18 Group: 9 0	Remark: BREAL MOTOR COUPL. REPL.	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-32-19 Group: 9 0	Remark: LANDING GEAR ON GRD OP.MOD.	COMPLETE	1275	09.06.2002	0						
On Condition			SB 525-32-20 Group: 9 0	Remark: LANDING GEAR BRAKE LINE REPL.	COMPLETE	1261	15.05.2002	0						
On Condition			SB 525-32-25 Group: 9 0	Remark: BEARING REPLACEMENT	N/A	1989	13.10.2005	0						
On Condition			SB 525-33-06 R1 Group: 9 0	Remark: EMER. LIGHTNING BATT.PACK UPGR	COMPLETE	2942	02.09.2014	3071						
On Condition			SB 525-33-07 Group: 9 0	Remark: CHART LIGHT MODIFICATION	N/A	0		0						
On Condition			SB 525-34-27 R1 Group: 9 0	Remark: GNX-XLS FAULT DETECTION	COMPLETE	1392	05.04.2003	0						
On Condition			SB 525-34-29 Group: 9 0	Remark: RATE GYRO RUDDER KICK	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-34-30 Group: 9 0	Remark: ART-2000-6 RADAR MODIFICATION	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-34-32 R1 Group: 9 0	Remark: AVIONIK MASTER SWITCH REPL.	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-34-33 Group: 9 0	Remark: KLN-90B SW MOD21/10 MOD	COMPLETE	824	19.05.2000	0						
On Condition			SB 525-34-33 R1 Group: 9 0	Remark: KLN-90B SW MOD21/10	COMPLETE	2942	20.08.2014	3071						
On Condition			SB 525-34-33 R2 Group: 9 0	Remark: KLN-90B SW MOD 21/10	COMPLETE	2942	20.08.2014	3071						
On Condition			SB 525-34-34 Group: 9 0	Remark: KLN-900 SW MODIFICATION	COMPLETE	824	19.05.2000	0						
On Condition			SB 525-34-35 Group: 9 0	Remark: BRNAV INCORPERATION	N/A	0		0						
On Condition			SB 525-34-36 Group: 9 0	Remark: EQUIPMENT NOT INSTALLED	COMPLETE	1392	05.04.2003	0						
On Condition			SB 525-34-38 R1 Group: 9 0	Remark: SHADIN ADC-200	N/A	1392	05.04.2003	0						
On Condition			SB 525-34-39 Group: 9 0	Remark: GNS-XLS SW MOD 4 UPGRADE	COMPLETE	824	19.05.2000	0						

transavia
Fluggesellschaft
Maintenance Review

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9 SB</u>														
On Condition			SB 525-34-41 Group: 9 0	Remark: RVSM OPERATION MOD.	COMPLETE	975	22.12.2000	0						
On Condition			SB 525-34-46 Group: 9 0	Remark: NOT APPLICABLE	COMPLETE	N/A	1342	29.10.2002	0					
On Condition			SB 525-34-61 Group: 9 0	Remark: MST-67A XPDR INSTALLATION	COMPLETE		1728	19.10.2004	0					
On Condition			SB 525-34-62 R1 Group: 9 0	Remark: GARMIN RADIO INST.	M/A	0		0						
On Condition			SB 525-34-84 R2 Group: 9 0	Remark: FMS-3000 WIDE AREA WAAS	N/A	0		0						
On Condition			SB 525-36-04 R1 Group: 9 0	Remark: PRECOOLER IMPROVEMENT	N/A	0		0						
On Condition			SB 525-52-05 R1 Group: 9 0	Remark: DOOR SEAL VALVE REPLA.	N/A	0		0						
On Condition			SB 525-52-07 Group: 9 0	Remark: TAILCONE BAGGAGE DOOR LATCH	N/A	0		0						
On Condition			SB 525-52-08 R1 Group: 9 0	Remark: IMPRO. CABIN ENTRY STEPS	N/A	0		0						
On Condition			SB 525-52-09 R1 Group: 9 0	Remark: CABIN DOOR ENTRTY HANDLE	N/A	0		0						
On Condition			SB 525-53-07 R2 Group: 9 0	Remark: AFT BAGGAGE SECTION SKI OPTION	N/A	0		0						
On Condition			SB 525-53-10 R1 Group: 9 0	Remark: TAILCONE AIR CONDITION INLET	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-53-10 R2 Group: 9 0	Remark: TAILCONE AIR CONDITOMN INLET	COMPLETE	1261	15.05.2002	0						
On Condition			SB 525-53-15 Group: 9 0	Remark: TAILCONE STRINGER RIVET INST.	COMPLETE	780	07.03.2000	0						
On Condition			SB 525-53-16 Group: 9 0	Remark: AFT FAIRING DOUBLER MOD.	COMPLETE	1103	25.09.2001	0						
On Condition			SB 525-53-17 Group: 9 0	Remark: NOSE WHEEL STEER BRACKET REPL.	COMPLETE	737	03.12.1999	0						
On Condition			SB 525-53-17 R1 Group: 9 0	Remark: NOSE WHEEL STEER BRACKET REPL.	COMPLETE	1103	25.09.2001	0						
On Condition			SB 525-53-18 R1 Group: 9 0	Remark: RIVET INSP./INST.	COMPLETE	1392	05.04.2003	0						
On Condition			SB 525-53-20 Group: 9 0	Remark: DISABLE COCKPIT MOUNTED RELIEF	N/A	2528	30.08.2007	0						

Registration: D-ITRA
Typ : CESSNA C525
Date : 03.06.25
Hours : 7622 h

Cycles Airframe : 6762
Engine No. 1 : 6762
Engine No. 2 : 6762
Page : 17

transavia
Fluggesellschaft
Maintenance Review

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>9 SB</u>														
On Condition			SB 525-53-20 R1 Group: 9 0	Remark: DISABLE COCKPIT MOUNTED RELIEF	N/A	2942	02.09.2014	3071						
On Condition			SB 525-54-04 R2 Group: 9 0	Remark: FIREWALL BOX REPAIR NACCELLES	N/A	0		0						
On Condition			SB 525-54-05 Group: 9 0	Remark: MID FIRERWALL FASTENER INSP.	N/A	2836	06.02.2012	0						
On Condition			SB 525-57-08 Group: 9 0	Remark: POLISHED LEADING EDGE WING TIP	N/A	0		0						
On Condition			SB 525-57-10 R1 Group: 9 0	Remark: KID PLATE CAP ADDITION	COMPLETE	824	19.05.2000	0						
On Condition			SB 525-57-12 Group: 9 0	Remark: LEADING EDGE TUBE REPL.	COMPLETE	1275	09.06.2002	0						
On Condition			SB 525-76-03 R2 Group: 9 0	Remark: ENG.SYNCHRONIZER CONTR. CABLE	COMPLETET	2851	13.08.2009	0						
On Condition			SB 525-76-04 R1 Group: 9 0	Remark: FWD THROTTLE CABLE REPL.	N/A	0		0						
On Condition			SB 525-76-05 R1 Group: 9 0	Remark: ENG.PWR CONTROL CABLE	N/A	0		0						
On Condition			SB 525-76-06 Group: 9 0	Remark: SAFE FLIGHT N1 COMPUTER	N/A	0		0						
On Condition			SB 525-78-05 R1 Group: 9 0	Remark: THRUST ATT. PADDLE BELLCRANK	COMPLETE	824	19.05.2000	0						
On Condition			SB 525-79-01 Group: 9 0	Remark: OIL PRESSURE TRANSMITTER	COMPLETE	455	20.12.1998	0						
On Condition			SB 525-80-02 Group: 9 0	Remark: STARTER GENERATOR INSP. REPL.	N/A	177	22.01.1998	0						
On Condition			SB 525-80-02 R2 Group: 9 0	Remark: STARTER GENERATOR INSP. REPL.	COMPLETE	284	19.06.1998	0						
On Condition			SB CIB-25-01 Group: 9 0	Remark: PAX SEAT QUICK RELEASE PIN	OPT NON MANDAT	0		0						
On Condition			SB CIB-25-02 Group: 9 0	Remark: TOILET SEAT MODIFICATION	N/A	0		0						
On Condition			SB CIB-28-01 Group: 9 0	Remark: FIRE SHUT OF VALVE GRD IMPRO.	N/A	0		0						
On Condition			SB CIB-34-02 Group: 9 0	Remark: GPS-4000S SW UPDATE	N/A	0		0						
On Condition			SB CIB-34-04 Group: 9 0	Remark: ROCKWELL ADAPTIVE FLIGHT DISP	N/A	0		0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9 SB</u>														
On Condition			SB FJ44-71-006 Group: 9 0	Remark: COMPRESSOR SECTION INSP.	N/A	0		0						
On Condition			SB FJ44-71-006 Group: 9 0	Remark: COMPRESSOR SECTION INSP.	N/A	0		0						
On Condition			SB FJ44-72-022 R1 Group: 9 0	Remark: REPAIR RH SERVICE ADAPTER BYPA	N/A	0		0						
On Condition			SB FJ44-72-022 R1 Group: 9 0	Remark: REPAIR RH SERVICE ADAPTER BYPA	N/A	0		0						
On Condition			SB FJ44-72-029 R3 Group: 9 0	Remark: 1ST LP TURBINE NOZZLE ASSY	N/A	0		0						
On Condition			SB FJ44-72-029 R3 Group: 9 0	Remark: 1ST LP TURBINE NOZZLE ASSY	N/A	0		0						
On Condition			SB FJ44-72-034 R6 Group: 9 0	Remark: ENG. GEARBOX ASSY	N/A	2942	20.08.2014	3071						
On Condition			SB FJ44-72-039 R3 Group: 9 0	Remark: ENG. HP COMPRESSOR ROTOR	N/A	0		0						
On Condition			SB FJ44-72-039 R3 Group: 9 0	Remark: ENG. HP COMPRESSOR ROTOR	N/A	0		0						
On Condition			SB FJ44-72-039 R4 Group: 9 0	Remark: HP COMPRESSOR ROTOR BACKWALL	N/A	0		0						
On Condition			SB FJ44-72-039 R4 Group: 9 0	Remark: HP COMPRESSOR ROTOR BACKWALL	N/A	0		0						
On Condition			SB FJ44-72-039 R4 Group: 9 0	Remark: ENG.HP TURBINE REPL. BLADES	N/A	0		0						
On Condition			SB FJ44-72-041 R4 Group: 9 0	Remark: ENG.HP TURBINE REPL. BLADES	N/A	0		0						
On Condition			SB FJ44-72-046 R5 Group: 9 0	Remark: INST. DIFFUSER/BAYPASS DUCT	N/A	2942	20.08.2014	3071						
On Condition			SB FJ44-72-046 R5 Group: 9 0	Remark: INST.DIFFUSER/BYPASS DUCT	N/A	2942	20.08.2014	3071						
On Condition			SB FJ44-72-050 R1 Group: 9 0	Remark: INST. DIFFUSER HOLLOW BOLT	N/A	2942	20.08.2014	3071						
On Condition			SB FJ44-72-051 R3 Group: 9 0	Remark: REWORK NAMEPLATE	N/A	0		0						
On Condition			SB FJ44-72-051 R3 Group: 9 0	Remark: REWORK NAMEPLATE	N/A	0		0						
On Condition			SB FJ44-72-052 R2 Group: 9 0	Remark: PEPLACE IP COMPRESSOR ROTOR	COMPLETE	2942	20.08.2014	3071						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9</u> <u>SB</u>														
On Condition			SB FJ44-72-052 R2 Group: 9 0	Remark: REPLACE IP COMPRESSOR	COMPLETE	2942	20.08.2014	3071						
On Condition			SB FJ44-72-054 R4 TO R6 Group: 9 0	Remark: ENG.GEARBOX ASSY	N/A	0		0						
On Condition			SB FJ44-72-054 R4 TO R6 Group: 9 0	Remark: ENG.GEARBOX ASSY	N/A	0		0						
On Condition			SB FJ44-72-066 R3 Group: 9 0	Remark: ENG.CARBON SEAL BEARING HOUSIN	N/A	0		0						
On Condition			SB FJ44-72-066 R3 Group: 9 0	Remark: ENG.CARBON SEAL BEARING HOUSIN	N/A	0		0						
On Condition			SB FJ44-72-076 Group: 9 0	Remark: ENG.COMPRESSOR STATOR	N/A	0		0						
On Condition			SB FJ44-72-076 Group: 9 0	Remark: ENG.COMPRESSOR STATOR	N/A	0		0						
On Condition			SB FJ44-72-076 R1 Group: 9 0	Remark: IP COMPRESSOR STATOR	N/A	0		0						
On Condition			SB FJ44-72-076 R1 Group: 9 0	Remark: IP COMPRESSOR STATOR	N/A	0		0						
On Condition			SB FJ44-72-079 R2 Group: 9 0	Remark: ENG.MPI TIME EXTENS. TAP	N/A	0		0						
On Condition			SB FJ44-72-079 R2 Group: 9 0	Remark: ENG.MPI TIME EXTENS. TAP	N/A	0		0						
On Condition			SB FJ44-72-081 R1 Group: 9 0	Remark: UPGRADE FJ44-1A GEARBOX	N/A	0		0						
On Condition			SB FJ44-72-081 R1 Group: 9 0	Remark: UPGRADE FJ44-1A GEARBOX	N/A	0		0						
On Condition			SB FJ44-72-083 R1,R3-R5 Group: 9 0	Remark: EMG.UPGRADE GEARBOX FJ44-1A	N/A	0		0						
On Condition			SB FJ44-72-083 R1,R3-R5 Group: 9 0	Remark: ENG.UPGRADE GEARBOX FJ44-1A	N/A	0		0						
On Condition			SB FJ44-72-087 R2-R5 Group: 9 0	Remark: ENG. BLEED VALVE SHAFT	N/A	0		0						
On Condition			SB FJ44-72-087 R2-R5 Group: 9 0	Remark: ENG. BLEED VALVE SHAFT	N/A	0		0						
On Condition			SB FJ44-72-092 Group: 9 0	Remark: 1ST LP TURBINE NOZZLE	N/A	0		0						
On Condition			SB FJ44-72-092 Group: 9 0	Remark: 1ST LP TURBINE NOZZLE	N/A	0		0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>9 SB</u>														
On Condition			SB FJ44-72-099 R1-R2 Group: 9 0 Remark: ENG. 6 BOLT SPINNER		N/A	0		0						
On Condition			SB FJ44-72-099 R1-R2 Group: 9 0 Remark: ENG. 6 BOLT SPINNER		N/A	0		0						
On Condition			SB FJ44-72-108 (R1) Group: 9 0 Remark: ACCESSORY DRIVE SHAFT		N/A	0		0						
On Condition			SB FJ44-72-108 (R1) Group: 9 0 Remark: ACCESSORY DRIVE SHAFT		N/A	0		0						
On Condition			SB FJ44-72-109 Group: 9 0 Remark: 1ST REDUCTION BEVEL GEAR BALL		N/A	0		0						
On Condition			SB FJ44-72-111 (R1-R2) Group: 9 0 Remark: 1ST LP TURBINE NOZZLE		N/A	0		0						
On Condition			SB FJ44-72-111 (R1-R2) Group: 9 0 Remark: 1ST LP TURBINE NOZZLE		N/A	0		0						
On Condition			SB FJ44-72-112 Group: 9 0 Remark: ROUTINE PERIODIC INSP.		N/A	0		0						
On Condition			SB FJ44-72-112 Group: 9 0 Remark: ROUTINE PERIODIC INSP.		N/A	0		0						
On Condition			SB FJ44-72-121 (R1) Group: 9 0 Remark: HP COMPRESSOR MOTOR		N/A	0		0						
On Condition			SB FJ44-72-121 (R1) Group: 9 0 Remark: HP COMPRESSOR ROTOR		N/A	0		0						
On Condition			SB FJ44-72-123 (R1) Group: 9 0 Remark: CANCELLED INNER GUIDED ROLLER BEARING		N/A	0		0						
On Condition			SB FJ44-72-123 (R1) Group: 9 0 Remark: CANCELLED INNER GUIDED ROLLER BEARING		N/A	0		0						
On Condition			SB FJ44-72-129 Group: 9 0 Remark: INNER GUIDED ROLLER BEARING 3.		N/A	0		0						
On Condition			SB FJ44-72-129 Group: 9 0 Remark: INNER GUIDED ROLLER BEARING 3.		N/A	0		0						
On Condition			SB FJ44-72-130 Group: 9 0 Remark: HP COMPRESSOR ROTOR		N/A	0		0						
On Condition			SB FJ44-72-130 Group: 9 0 Remark: HP COMPRESSOR MOTOR		N/A	0		0						
On Condition			SB FJ44-720-50 R1 Group: 9 0 Remark: INST.DIFFUSER HOLLOW BOLT		N/A	2942	20.08.2014	3071						
On Condition			SB FJ44-77-008 R3 Group: 9 0 Remark: REPL. ITT PROBES WITH MID			0		0						

Registration: D-ITRA
Typ : CESSNA C525
Date : 03.06.25
Hours : 7622 h

Cycles Airframe : 6762
Engine No. 1 : 6762
Engine No. 2 : 6762
Page : 21

transavia
Fluggesellschaft
Maintenance Review

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>9 SB</u>														
On Condition	SB FJ44-77-008 R3 Group: 9 0			Remark: REPLACE ITT PROBES WITH MID	N/A	0		0						
On Condition	SB FJ44-79-011 (R1-R4) Group: 9 0			Remark: OIL MAGNET SELF CLOSING VALVE	N/A	2942	02.02.2014	3071						
On Condition	SB FJ44-79-011 (R1-R4) Group: 9 0			Remark: OIL MAGNET SELF CLOSING VALVE	N/A	2942	02.09.2014	0						
On Condition	SB FJ44-79-015 Group: 9 0			Remark: OIL LUBE & SCAVENGE PUMP ASSY	N/A	0		0						
On Condition	SB FJJ44-72-109 Group: 9 0			Remark: 1ST REDUCTION BEVEL GEAR BALL	N/A	0		0						
On Condition	SB FJJ44-79-015 Group: 9 0			Remark: OIL LUBE & SCAVENGE PUMP ASSY	N/A	0		0						
On Condition	SB525-25-34 Group: 9 0			Remark: OPTIONAL HEADSET MOUNTING	N/A	0		0						
On Condition	SB525-33-10 Group: 9 0			Remark: LED WIGTIP LIGHTS	NOT INSTALLED	0		0						
On Condition	SL 44-71-153 Group: 9 0			Remark: VOLCANIOSH ASH CONTAMINATION	N/A	0		0						
On Condition	SL 44-71-153 Group: 9 0			Remark: VOLCANIC ASH CONTAMINATION	N/A	0		0						
On Condition	SL 44-72-306 R1 Group: 9 0			Remark: ENG.LP REAR BEARING SEAL RETAI	N/A	0		0						
On Condition	SL 44-72-306 R1 Group: 9 0			Remark: ENG.LP REAR BEARING SEAL RETAI	N/A	0		0						
On Condition	SL 525-03-01 R1 Group: 9 0			Remark: STC REPL CIL-03-01 03JUN13	N/A	0		0						
On Condition	SL 525-05-03 R1 Group: 9 0			Remark: 05SL-03:525R1 NEW TASK 525 BASED INSP.PROG.	COMPLETE	2528	30.08.2007	0						
On Condition	SL 525-05-05 Group: 9 0			Remark: PRECOOLER LIFE LIMITS	INFO NOTED	0		0						
On Condition	SL 525-20-01 R18 Group: 9 0			Remark: CERTIFICATION NONDESTRUCTIVE	N/A	0		0						
On Condition	SL 525-20-05 Group: 9 0			Remark: 20SL-05 ELEK.CONNECTOR REPLACEMENT	COMPLETE	1261	15.05.2002	0						
On Condition	SL 525-20-06 Group: 9 0			Remark: INFO NOTED CESSNA STANDARD PRACTISES	INFO NOTED	0		0						
On Condition	SL 525-23-05 Group: 9 0			Remark: 23SL-05 BENDIX KY196A-9 VHF COMM TRANS	COMPLETE	824	19.05.2000	0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9 SB</u>														
On Condition			SL 525-23-06 Group: 9 0	Remark: 23SL-06 BENDIX KY196A VHF COMM.TRANS	COMPLETE	824	19.05.2000	0						
On Condition			SL 525-23-11 Group: 9 0	Remark: ATG 5000 COM UPGRADE	NOT INSTALLED	0		0						
On Condition			SL 525-24-03 R1 Group: 9 0	Remark: 24SL-03 : 525R1 IGNITER CONTROL P/CB INSP.	COMPLETE	1261	15.05.2002	0						
On Condition			SL 525-24-10 Group: 9 0	Remark: BATTERY TEM INDICATOR	NOTED	0		0						
On Condition			SL 525-25-03 R1 Group: 9 0	Remark: 25SL-03 : 525R1 LH TOILET SEAT BELT INSP.	COMPLETE	824	19.05.2000	0						
On Condition			SL 525-25-05 Group: 9 0	Remark: 25SL-05 INSP. BACKREST LATCH PLATES	COMPLETE	2927	29.09.2010	3050						
On Condition			SL 525-27-01 Group: 9 0	Remark: ELEV.ELEC.TRIM TAB ACTUATOR	COMPLETE	1392	05.04.2003	0						
On Condition			SL 525-27-04 R1 Group: 9 0	Remark: FLAP PUSHROD SAFETY WIRE INSP.	COMPLETE	2803	29.10.2008	0						
On Condition			SL 525-27-09 Group: 9 0	Remark: OPT.NOT IMPLEMN SPEEDBRAKE ACTUATOR SCREW REPL		0		0						
On Condition			SL 525-30-02 R1 Group: 9 0	Remark: COMPLETE L&RH WINDSHIELD ANTI ICE CONTR		455	20.12.1988	0						
On Condition			SL 525-31-02 Group: 9 0	Remark: N/A ANNUNCIATOR PANEL REPLACEMENT		0		0						
On Condition			SL 525-32-12 Group: 9 0	Remark: COMPLETE MLG TRAINLING LINK/SPACER GAP		455	20.12.1998	0						
On Condition			SL 525-32-14 Group: 9 0	Remark: COMPLETE NOSE GEAR STEERING BUNGEE INSP		455	20.12.1998	0						
On Condition			SL 525-32-15 Group: 9 0	Remark: COMPLETE NLG TIRE INSPECTION		1190	26.03.2002	1258						
On Condition			SL 525-32-17 R1 Group: 9 0	Remark: N/A NLG ICE PROTECTION BOOT INST.		0		0						
On Condition			SL 525-32-19 Group: 9 0	Remark: COMPLETE GOODRICH SL 2056		2742	24.07.2008	0						
On Condition			SL 525-32-20 Group: 9 0	Remark: COMPLETE MLG DOOR PUSHROD SAFTY WIRE IN		2803	29.10.2008	0						
On Condition			SL 525-32-23 R2 Group: 9 0	Remark: COMPLETE EMER.GEAR RELEASE INSP.		2836	06.02.2012	0						
On Condition			SL 525-32-27 Group: 9 0	Remark: INFO IMPLEMTD MAIN LFG GEAR REPAIR		0		0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO TSO	MBO MSO	CBO CSO	TLL TSN	MLL MSN	CLL CSN
<u>9 SB</u>														
On Condition			SL 525-34-04 Group: 9 0	COMPLETE Remark: KLN89B,KLN90B,KLN900 GPS	N/A	134	28.10.1997	0						
On Condition			SL 525-34-08 Group: 9 0	Remark: BFGOODRICH SB 78A	COMPLETE	564	12.04.1999	0						
On Condition			SL 525-34-09 Group: 9 0	Remark: BF GOODRICH SB #79	COMPLETE	824	19.05.2000	0						
On Condition			SL 525-34-10 Group: 9 0	Remark: GNS-XLS FMS MOD 7	COMPLETE	1392	05.04.2003	0						
On Condition			SL 525-34-14 R1 Group: 9 0	Remark: HONEYWELL SB 182A-16 RADAR IND	COMPLETE	1696	26.08.2004	0						
On Condition			SL 525-35-02 Group: 9 0	COMPLETE Remark: EQUIPMENT NOT INSTALLED	N/A	1261	15.05.2002	0						
On Condition			SL 525-35-05 Group: 9 0	Remark: OXYGEN BOTTLE INSP.	N/A	0		0						
On Condition			SL 525-35-06 Group: 9 0	Remark: OXYGEN MXH-35-240	N/A	2836	06.02.2012	0						
On Condition			SL 525-35-06 R2 Group: 9 0	Remark: OXYGEN MXH-35-240	COMPLETE	2942	20.08.2014	3071						
On Condition			SL 525-36-01L R1 Group: 9 0	Remark: PRECOOLER INSP. MODEL 525	COMPLETE	2209	06.09.2006	0						
On Condition			SL 525-36-01R R1 Group: 9 0	Remark: PRECOOLER INSP.	COMPLETE	2209	06.09.2006	0						
On Condition			SL 525-36-02 Group: 9 0	Remark: TAILCONE BLEED AIR CHECK		0		0						
On Condition			SL 525-53-05 Group: 9 0	Remark: INTERCOSTAL DRAINAGE PATH INSP	COMPLETE	4213	27.05.2017	0						
On Condition			SL 525-53-06 Group: 9 0	Remark: UPPER TAILCONE SKIN INSP	COMPLETE	5262	30.10.2019	5031						
-50			SL 525-53-07 Group: 9 0	Remark: ACCESS PANEL DRAIN HOLE INST.		7272	26.10.2023	6542	300					
On Condition			SL 525-57-02 Group: 9 0	Remark: ACCESS DOOR DRAINAGE IMPR.	COMPLETE	2209	06.09.2006	0						
On Condition			SL 525-72-06 Group: 9 0	COMPLETE Remark: WILLIAM ROLLS SL44-72-72	N/A	564	12.04.1999	0						
On Condition			SL 525-72-09 Group: 9 0	Remark: WILLIAMS ROLLS SB FJ44-72-052	COMPLETE	1392	05.04.2003	0						
On Condition			SL 525-99-02 R5 Group: 9 0	Remark: CANCELS SL525-99-02 R4	N/A	0		0						

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN
<u>9</u> <u>SB</u>														
On Condition			SL 525-99-05 Group: 9 0	Remark: CESSNA PART NUMBER	N/A	0		0						
On Condition			SL 525-99-06 Group: 9 0	Remark: CESSNA SERVICE DOCUMENT	N/A	0		0						
On Condition			SL CIL-03-01 Group: 9 0	Remark: STC	N/A	0		0						
On Condition			SL CIL-20-01 Group: 9 0	Remark: CERTIFICATION NONDESTRUCTIVE	N/A	0		0						
On Condition			SL CIL-20-01 R2 Group: 9 0	Remark: CERTIFICATION NONDESTRUCTIVE	N/A	0		0						
On Condition			SL CIL-21-01 Group: 9 0	Remark: SIEHE LTA D-2013-153 COMPRESSOR MOTOR BRUSHES LIFEL	N/A	0		0						
On Condition			SL CIL-26-01 Group: 9 0	Remark: FIRE EXT GROUND STUD TORQUING	N/A	0		0						
On Condition			SL CIL-30-01 R1 Group: 9 0	Remark: ICE & RAIN PROTECTION	N/A	0		0						
On Condition			SL CIL-31-01 Group: 9 0	Remark: CVR NOT INST INDICATING CVR RECORDING SYS		0		0						
On Condition			SL CIL-32-01 Group: 9 0	Remark: LANDING GEAR NOSE WHEEL IMPRO	N/A	0		0						
247			SL CIL-32-03 Group: 9 0	Remark: NLG UPLOCK ROLLER BRAKET INSP.		7569	31.07.2024	6725	300					
On Condition			SL CIL-32-04 Group: 9 0	Remark: WIRELESS TIRE PRESS. MONITORIN	N/A	0		0						
On Condition			SL CIL-32-04 Group: 9 0	Remark: WIRELESS TIRE PRESS MONITORING	NOT INSTALLED	0		0						
On Condition			SL CIL-32-06 Group: 9 0	Remark: WIRELESS TIRE PRESSURE SENSOR	NOT INSTALLED	0		0						
On Condition			SL CIL-33-01 Group: 9 0	Remark: RADIANT PWRCORP. CBS28 EMERBAT	N/A	0		0						
On Condition			SL CIL-34-04 Group: 9 0	Remark: TDR-94/94D XPDR ALL-CALL	N/A	0		0						
On Condition			SL CIL-35-01 Group: 9 0	Remark: BE AEROSPACE SB 118077-35-01	N/A	2942	02.09.2014	3071						
On Condition			SL CIL-35-05 Group: 9 0	Remark: ZODIAC OXYGEN	N/A	0		0						
On Condition			SL CIL-52-01 Group: 9 0	Remark: DOORS- EMER. DOORS INSP.	COMPLETE	2942	20.08.2014	0						

Registration: D-ITRA
Typ : CESSNA C525
Date : 03.06.25
Hours : 7622 h

Cycles Airframe : 6762
Engine No. 1 : 6762
Engine No. 2 : 6762
Page : 25

transavia
Fluggesellschaft
Maintenance Review

TGO	MGO	CGO	Description	P/N	S/N	TAI	DAI	CAI	TBO	MBO	CBO	TLL	MLL	CLL
									TSO	MSO	CSO	TSN	MSN	CSN

9
SB

On Condition	SL CIL-52-02		INFO RCVD	0	0									
	Group: 9 0	Remark: EMERG DOOR INSP												
On Condition	SL CIL-52-03		COMPLETED	7272	26.10.2023	6542								
	Group: 9 0	Remark: EMERG ESCAPE HATCH INSP												
On Condition	SL CIL-99-01		N/A	0	0									
	Group: 9 0	Remark: CORROSION INHIBIT COMPOUNDS												
On Condition	SL CIL-99-01 R1		COMPLETE	2942	20.08.2014	3071								
	Group: 9 0	Remark: CORROSION INHIBIT COMPOUNDS												
On Condition	SL CIL-99-02		N/A	0	0									
	Group: 9 0	Remark: AVOID OP.RWY.THREATED DE-ICE												
On Condition	SL CIL-99-03 R1		N/A	0	0									
	Group: 9 0	Remark: CORROSION PREVENTION CONTROL												
On Condition	SL CIL-99-03-R02		PFMD ACC DOC INSP	0	0									
	Group: 9 0	Remark: CORROSION PREVENTION PROGRAM												
On Condition	SL CIL-99-04R1		INFO IMPLEMENTD	0	0									
	Group: 9 0	Remark: CESVIEW LIBRARY UPDATES												
On Condition	SL ICA-525-21-00001A		REV IMPLEMENTED	0	0									
	Group: 9 0	Remark: AIR CONDITIONER ICA SUPPLEMENT												
On Condition	SL ICA-525-33-00001		NOT INSTALLED	0	0									
	Group: 9 0	Remark: LED WINGTIP LIGHT UPDATE												

First Character: T?? = hour
M?? = month
C?? = Cycle
D?? = date (DD.MM.YYYY)
***** = overdue

Next character: ?BO = between overhaul
?LL = life limit
?SO = since overhaul
?SN = since new
?GO = remainig
?AI = at installation

This records are checked by:_____
Date:_____